

# TOTO

## THÔNG BÁO

V/v: ĐIỀU CHỈNH GIÁ SỬA CHỮA DỊCH VỤ 2023

Kính gửi: Quý khách hàng của TOTO Việt Nam

Căn cứ theo Nghị định 15/2022/NĐ-CP quy định mức giảm thuế giá trị gia tăng, áp dụng từ ngày 01/07/2023 đến hết 31/12/2023.

Công ty TNHH TOTO Việt Nam xin thông báo tới Quý khách hàng bảng giá sửa chữa dịch sau khi áp dụng 8% thuế GTGT như sau:

### 1. Phí sửa dịch vụ.

Đơn giá: VNĐ

STT	Loại sản phẩm	Vệ sinh, nước vào/ra yếu	Chảy nước, rò điện, xả nặng tay...	Xả yếu, tháo lắp sản phẩm	Thay pin sản phẩm	Cài đặt chế độ sản phẩm	Thay thế không cần tháo sản phẩm	Thay thế cần tháo sản phẩm	Phí thay điều khiển	Phí kiểm tra
1	Bồn cầu	196,363	196,363	392,727	-	-	196,363	392,727	-	147,273
2	Chậu rửa	196,363	196,363	196,363	-	-	196,363	196,363	-	
3	Sen tắm, vòi rửa	196,363	196,363	196,363	-	-	196,363	196,363	-	
4	Thân sứ tiêu nam	196,363	196,363	392,727	-	-	196,363	392,727	-	
5	Cảm ứng, van xả tiêu nam	196,363	196,363	196,363	196,363	-	196,363	392,727	-	
6	Vòi tự động	196,363	196,363	196,363	196,363	-	196,363	392,727	-	
7	Nắp rửa cơ Nắp đóng êm	196,363	196,363	196,363	-	-	196,363	196,363	-	
8	Nắp rửa điện tử	196,363	392,727	196,363	196,363	392,727	392,727	392,727	147,273	
9	Bồn cầu điện tử	392,727	392,727	687,273	196,363	392,727	392,727	687,273	147,273	
10	Bồn tắm thường	196,363	196,363	392,727	-	-	196,363	687,273	-	
11	Bồn tắm điện	392,727	196,363	392,727	-	-	196,363	687,273	-	
12	Máy sấy tay	196,363	196,363	196,363	-	-	196,363	196,363	-	

\*Nếu trên 1 sản phẩm mà phát sinh nhiều hơn 1 dịch vụ sửa tại 1 thời điểm, phí sẽ được tính bằng phí của 1 dịch vụ có giá cao nhất.

### 2. Phí đi lại.


Từ 25 ~ 50 km	Từ 51 ~ 75 km	Từ 76 ~ 100 km	Trên 100 km
417,273	854,182	1,276,363	1,669,091

### 3. Phí phụ kiện.

Căn cứ theo bảng giá phụ kiện do TOTO Việt Nam quy định.

TOTO Việt Nam sẽ tiếp tục nỗ lực để đem đến các sản phẩm và dịch vụ tốt nhất cho khách hàng.

Đại diện công ty TNHH TOTO Việt Nam





## ANNOUNCEMENT

Subject: 2023 REPAIR SERVICE PRICE LIST ADJUSTMENT

To: TOTO Vietnam Customers,

Based on Decree 15/2022/ND-CP on guiding the implementation and reduction of value-added tax (VAT) from 01/07/2023 until 31/12/2023.

TOTO Vietnam Co., Ltd would like to inform the adjusted price list of Repair Service with 8% in VAT as follows

### 1. Service fees

Unit: VND

No	Type Products	Cleaning, water filling in/ running out weakly	Water/ electric leakage, Flushing heavily	Flushing weakly, Removing & resetting required	Change batteries	Setup program	Parts replacement without taking out product	Parts replacement need taking out product	Change remote controller	Checking fee
1	Closet	196,363	196,363	392,727	-	-	196,363	392,727	-	147,273
2	Lavatory	196,363	196,363	196,363	-	-	196,363	196,363	-	
3	Faucet Lavatory & Shower	196,363	196,363	196,363	-	-	196,363	196,363	-	
4	Urinal body	196,363	196,363	392,727	-	-	196,363	392,727	-	
5	Urinal Sensor & Flush valve	196,363	196,363	196,363	196,363	-	196,363	392,727	-	
6	Auto Faucet	196,363	196,363	196,363	196,363	-	196,363	392,727	-	
7	Eco-washer Soft-closing cover	196,363	196,363	196,363	-	-	196,363	196,363	-	
8	Washlet	196,363	392,727	196,363	196,363	392,727	392,727	392,727	147,273	
9	Neorest	392,727	392,727	687,273	196,363	392,727	392,727	687,273	147,273	
10	Normal Bathtub	196,363	196,363	392,727	-	-	196,363	687,273	-	
11	Electronic Bathtub	392,727	196,363	392,727	-	-	196,363	687,273	-	
12	Hand Dryer	196,363	196,363	196,363	-	-	196,363	196,363	-	

\*In case with one product but arising more than 01 service at the same time, cost will be charge by one highest service which provided for this product

### 2. Transportation fees

From 25 ~ 50 km	From 51 ~ 75 km	From 76 ~ 100 km	Over 100 km
417,273	854,182	1,276,363	1,669,091

### 3. Spare part price

Spare part price is based on Spare Part Retail Price list issued by TOTO Vietnam.

As always, TOTO Vietnam is committed to providing superior products and service to our customers.

TOTO Vietnam representative  
YUSUKE SASAYA  
Sales Director

